ENTERED HATER MEL	L REPORT Start (and No. W062230
4406 STATE OF W	L REPORT Start (3rd No. W062230 ASHINGTON Water Right Fermit No. B LENZ PL LANGLEY, WA 98260-
(1) OWNER: Name STOVEL, MARK Address 5677 (- SE 1/4 NM 1/4 Ser S T 29 N R 3F NM
(2) LOCATION OF WELL: County ISLAND (2a) STREET ADDRESS OF WELL (or nearest address) ANDREASON RD	36 1/4 NH 1/4 300 3 1 12 NH N 11 NH
(3) PROPOSED USE: DOMESTIC	(10) WELL 106
(4) TYPE OF WORK: Owner's Number of well (If more than one) 1 NEW WELL Method: ROTARY (5) DIMENSIONS: Diameter of well 6 inches Drilled 102 ft. Depth of completed well 74.5 ft.	Formation: Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change in formation.
(5) DIMENSIONS: Diameter of well 6 inches Drilled 102 ft. Depth of completed well 74.5 ft.	MATERIAL FROM TO
(6) COMSTRUCTION DETAILS: Casing installed: 6 " Dia. from +1.5 ft. to 72 ft. WELDED "Dia. from ft. to ft. Dia. from ft. to ft. Perforations: YES	BROWN SAND
- P P L J ATO OCTADU DEDE	GRAY CLAY SAND
size of perforations 1/4 in. by 1 in. 120 perforations from 60 ft. to 65 ft. perforations from ft. to ft.	RECEIVED
perforations from II. to II.	JUN 1 2 1995
Screens: YES Manufacturer's Name Type STAINLESS STEEL Diam. 6 slot size 20 from 69.5 ft. to 74.5 ft.	DEPT. OF ECOLOGY
Olam. Slot Size from it, to it.	DEF 7. OF ECOLOGY
Gravel packed: NO Size of gravel Gravel placed from ft. to ft.	
Surface seal: YES To what depth? 18 ft. Material used in seal BENTONITE Did any strata contain unusable water? NO Type of water? Depth of strata ft. Method of sealing strata off	
(7) PUMP: Manufacturer's Name AERMOTOR Type SUBMERSIBLE H.P. 1.5	
(8) WATER LEVELS: Land-surface elevation above mean sea level	
Static level 42 ft. below top of well Date 06/01/95 Artesian Pressure lbs. per square inch Date	
Artesian water controlled by	Mork started 05/30/95 Completed 06/01/95
(9) WELL TESTS: Drawdown is amount water level is lowered below static level. Was a pump test made? YES If yes, by whom? JERRY BACUS Yield: 24 gal./min with ft. drawdown after 4 hrs.	WELL CONSTRUCTOR CERTIFICATION: I constructed and/or accept responsibility for construction of this well, and its compliance with all Washington well construction standards. Materials used and the information reported above are true to my best knowledge and belief.
Recovery data Time Mater Level Time Water Level Time Water Level	•
	ADDRESS 556 ERSHIG RD. BOW, WA
Date of test Bailer test 20 gal/min, 13 ft. drawdown after 1 hrs. Air test gal/min w/ stem set at ft. for hrs	
Air test gal/min. w/ stem set at ft. for hrs Artesian flow g.p.m. Date Temperature of water Was a chemical analysis made? YES	! Contractor's

WELL SITE MEETS ALL SIGHTING CRITERIA UNDER I.C.C. 8.09 BASED ON INFORMATIO SUPPLIED BY THE OWNER OR OWNER'S AUTHORIZED REPRESENTATIVE.



Well Tagging Form

Unique Well Tag No: BCB 765

RECORD VERIFICATION (check √one)

Well Report available (please attach this form to the well report and submit it to the Ecology Regional Office near you).

If a well report is not available, please complete a "Water Well Report for an Existing Well" form. This form is available at Ecology's headquarters office. Do not use this form for wells that do not have a Water Well Report.

WELL OWNERSHIP, IF DIFFERENT FROM WELL REPORT	
First Name: Stovel Water System Association	
Street Address: 5021 Lone LaKe Road	
City: Langley State: WA 98260	
LOCATION OF WELL, IF DIFFERENT FROM WELL REPORT	
Well Address: Parcel R32405-221-0290 Loan Lake Road	
City: Langley County: Is/and	
T. 29 N. R. 3 E W.M. Sec. 5 NW 1/2 of the 5W	
Latitude $\frac{48}{122}$ $\frac{1.631256}{27.70975}$ " Longitude $\frac{122}{27.70975}$ "	
Elevation at land surface 9 f feet/meters (circle one)	
SEE DACK SIDE OF DAGE	

SEE BACK SIDE OF PAGE...



